Oil Field Environmental Incident Summary

Responsible Party: RIM OPERATING, INC. **Well Operator:** RIM OPERATING, INC.

Well Name: LARSON 41-30

Field Name: GREAT NORTHERN Well File #: 19573

Date Incident:12/21/2014Time Incident:11:00Facility ID Number:County:BOTTINEAUTwp:160Rng:83Sec:30Qtr:

Location Description:

Submitted By: Troy Johnson Received By:

Contact Person: Ken Read

5 INVERNESS DRIVE EAST ENGLEWOOD, CO 80112

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

Spilled Units Recovered Units Followup Units

15 Barrels 10 barrels

Oil Brine

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 4/11/2016 Clean Up Concluded: 12/29/2014

Risk Evaluation:Not Applicable

Areal Extent:

Potential Environmental Impacts:

Not Applicable

Action Taken or Planned:

We are installing a check valve to keep water from other location from free flowing into this tank.

Wastes Disposal Location: Wastes will be put in a recovery tank on location.

Agencies Involved: Scott Dihle with NDIC was notified by phone yesterday.

Updates

Date: 12/22/2014 Status: Reviewed - Assigned to Other Agency Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to tank overflow, remained on location within the diking according to the report. NDIC retains oversight.